Enhancing safety for the EOT crane operator

Situation

- Structural cracks were discovered in the connection between the operator cabin and the crane.
- The earliest available maintenance window was 6–8 months away.
- Operational safety needed to be ensured in the meantime.

Solution

- Deployed 16 sensor probes on the cabin's structural components.
- Enabled continuous, real-time monitoring with daily condition updates.
- Set up **automated email alerts** to flag significant crack growth.













Enhancing safety for the EOT crane operator

Results

- Villari system detected major crack progression within 3 months.
- Prompt action was taken: the crane was shut down and emergency repairs carried out.
- A potentially life-threatening incident was averted.













